

# **DIA-COME Kits - Content**

## DIA-COME C2 Kits – useful options for most common applications

#### For the measurement of internal- and external Ø:

### C2-Kit1 and C2-Kit1-S - Small Diameters - For all C2 Measuring Tables

• 2 CO-MI5-48-S Flat Bottom Measuring Contact, Ø=5mm, L=48mm

2 CO-A44-S Adapter, L=44mm, short

2 CO-MT-S Small Table for small components
1 CO-MH38 Measuring Contact Support, 38 mm

1 CO-CP
Clamping Pin for Measuring Contact Support

#### C2-Kit2 - Big Diameters - Only for C2 and C2 Al Measuring Tables

1 CO-MH110 Measuring Contact Support, 110 mm

1 CO-CP Clamping Pin for Measuring Contact Support

## C2-Kit3 - Flat Bottom - Only for C2 and C2 Al Measuring Tables

1 CO-MI10-25-FB
2 CO-MI10-52-FB
Flat Bottom Measuring Contact, Ø=10mm, L=25mm
Flat Bottom Measuring Contact, Ø=10mm, L=52mm

## For Gear Gauging:

#### C2-ZM Kit1 and C2-ZM Kit1-S – small components – For all C2 Measuring Tables

2 CO-A44-S
Adapter, L=44mm, short

2 CO-MT-S
Small Table for small components

1 CO-MH38-S Measuring Contact Support, 38 mm, short
1 CO-CP Clamping Pin for Measuring Contact Support

## C2-ZM Kit2 – high components – For all C2 Measuring Tables

2 CO-ZMS52
Support for Gear Gauges, L=52mm

### C2-ZM Kit3 – adjustable Stopp – For all C2 Measuring Tables

1 CO-STA50
Adjustable Stop, L=50mm; Adjusting range 28mm

• 1 CO-MI16-52 Measuring Contact, Ø=16mm, L=52 mm

#### C2-ZM Kit4 - ball anvils - For all C2 Measuring Tables

2 CO-ST60-M2,5
Fixed Stop L=60mm, M2.5

## C2-ZM JS Kit1 – very big diameters – Only for C2 JS Measuring Tables

1 CO-MH110 Measuring Contact Support, 110 mm

1 CO-CP Clamping Pin for Measuring Contact Support





# **DIA-COME KITs - Content**

For 3-Point-Measuring Tables

## DIA-COME C3 Kits – useful options for most common applications

#### For the measurement of internal- and external Ø:

#### C3-Kit1 and C3 Kit1-S - Small diameters - Only for C3-45, C3-90, C3 AL, C3 JS Tables

3 CO-MI5-48-S Flat Bottom Measuring Contact, Ø=5mm, L=48mm

3 CO-A29-S Adapter, L=29mm, short

2 CO-MH38-S Measuring Contact Support, 38mm, short

1 CO-MT-S
1 CO-MT-S-C3
Small Table for small components
Small Table for small components

2 CO-CP
Clamping Pin for Measuring Contact Support

### C3-Kit2 – Grooves with max.depth of 2.5 mm – For all C3 Measuring Tables

1 CO-MI4,6-45
2 CO-MI4,6-36
Measuring Contact, Ø=4,6mm, L=45mm, for Grooves
Measuring Contact, Ø=4,6mm, L=36mm, for Grooves

#### C3-Kit3 - Large diameters - Only for C3 JS Measuring Tables

1 CO-MH150
1 CO-CP
Measuring Contact Support, L = 150 mm
Clamping Pin for Measuring Contact Support

All C2- and C3 Measuring tables are also available as Inch (3/8") versions. The pricing is the same as for the metrical measuring tables. Examples for order codes: C2 Base-Z, C2-ZM AL-Z or C3 JSL-Z.

All tables and Kits w/o indicator

